

# Guide to machining plastic parts

Metric system

**Specifications to consider when machining  
high-performance thermoplastic parts,  
provided by the Technical Services Department**

# Table of contents

## 01 MCG STOCK SHAPES

---

Machining instructions for MCG stock shapes 3

## 02 COOLING

---

Cooling plastics 4

## 03 SAWING

---

Cutting tools 5

Data sawing 6

Troubleshooting sawing 6

## 04 DRILLING

---

Drilling 7

Data drilling 8

Troubleshooting drilling 9

## 05 TURNING

---

Tapping/ turning threats 10

Turning tips 11

Troubleshooting turning 11

Data turning 12

## 06 MILLING

---

Milling 13

Data milling 14

## 07 TOLERANCES

---

Best tolerances at MCG engineered solutions 15

## 08 THREAD INSERTS / DEBURRING

---

Thread inserts 16

Deburring 16

## 09 GENERAL RULES

---

General rules 17

Solution example 17

## 10 ANNEALING

---

Better flatness and tighter tolerances 18

Annealing tips 18

Recommended annealing procedure 18

## 11 SUMMARY


---

Summary 19

# Machining instructions for MCG stock shapes

The stock shapes of Mitsubishi Chemical Group (MCG) Advanced Materials Division can easily be machined on ordinary metalworking and in some cases on woodworking machines. However, there are some points, which are worth noting to obtain improved results.

- Tools must be always kept sharp and smooth; specific polymer group determine the type of tools to be used.
- Feed rates should be as high as possible.
- Tools must have sufficient clearance so that the cutting edge only comes in contact with the plastics material.
- A good swarf removal from the tool must be assured.
- Coolants should be applied for operations where plenty of heat is generated (e.g. drilling).



## Keep it cool!

---

Due to poor thermal conductivity and lower melting properties the main skill is to avoid heat build up and evacuate swarf. This avoids deformation, stress build up or even melting.

- When machining Nylons, UHMW-PE and softer materials- go for maximum feed and speed to get swarf away from tool and avoid swarf build up or wrap around.
- Select tools with large clearance to allow swarf evacuation and deeper cuts.
- Use milling cutters with two or three flute with higher helix.
- Try to use air blast or vacuum venturi.
- HSS works well but solid carbide is stiffer.
- Try to use air blast.
- On glass or carbon fiber use carbide, reduce speed and increase feed rates.



**Meech air blasters  
are ideal**

## Cooling plastics

---



Coolants are generally not required for most machining operations (not including drilling and parting off). However, for optimum surface finishes and close tolerances, nonaromatic, water soluble coolants are suggested. Spray mists and pressurized air are very effective means of cooling the cutting interface. Mineral oil based cutting fluids, although suitable for many metals and plastics, may contribute to stress cracking of amorphous plastics such as Altron™ PC, Sultron® PPSU, Duratron® U1000 PEI, and Sultron® PSU.

If using coolant on amorphous materials wash immediately in Isopropyl alcohol and pure water post machining!

## Cutting tools

The cutting (polymer) material naturally has a serious effect on the service life of the tool. The MCG Advanced Materials Division recommends the use of HSS, carbide, diamond coated, PCD or CVD cutting tools.

- HSS- High-speed Steel tools work well with many plastics.
- Carbide tools are preferred for longer production runs
- Polycrystalline diamond (PCD) or Chemical Vapour Deposition (CVD) diamond tip tooling are essential when machining glass and/ or carbon fiber reinforced or graphite filled materials.
- Machining Duratron® CU60 PBI, Duratron® PI or Fluorosint® MT-01 PTFE, Polycrystalline diamond tooling provides optimum results, carbide tipped tools can then be used in case of very short production runs.

## Billeting/ Cutting


- Circular, band, reciprocating and guillotine saws are generally suitable for cutting thermoplastics
- Set of teeth (clearance between teeth side and body of cutter) must be as large as possible to prevent material closing and trapping blade
- Teeth per inch (TPI) must be suited for material:
  - soft low temperature materials need low TPI
  - filled and thinner materials require higher TPI

Reinforced materials such as Ertalon® 66 GF30 PA66, Duratron® T4301 PAI, Duratron® T4501 PAI, Duratron® T5530 PAI, Ketron® HPV PEEK, Ketron® GF30 PEEK, Ketron® CA30 PEEK Techtron® HPV PPS, Semitron® ESd 410C PEI and Semitron® ESd 520HR PAI are preferably cut with a band saw with a tooth pitch of 4 to 6 mm (Duratron® CU60 PBI, Duratron® PI and Fluorosint® MT- 01: 2-3 mm).


Do not use standard circular saws as this usually leads to cracks!

## Clamping tools

- Plastics are more 'elastic' so squeeze when clamped
- They can bow more easily
- Less force required to cut and there
- Vacuum systems work well for routing and light milling
- Double sided tape can be used for small thin parts
- Invest in high quality clamps for routing and milling



# Data sawing



	$\alpha_c$	$\gamma_c$	$t_c$	$v_c$	$\alpha_b$	$\gamma_b$	$t_b$	$v_b$
Ertalon® PA / Nylatron® PA, TIVAR® UHMW-PE	10 - 15	0 - 15	8 - 45	1,000- 3,000	25 - 40	0 - 8	4 - 10	50 - 500
Ertacetal® POM, Semitron® ESd 225	10 - 15	0 - 15	8 - 45	1,000- 3,000	25 - 40	0 - 8	4 - 10	50 - 500
Ertalylte® PET, Duratron® T4203 / 4503 PAI, Ketron® 1000 PEEK, Ketron® TX PEEK	10 - 15	0 - 15	8 - 25	1,000- 3,000	25 - 40	0 - 8	4 - 10	50 - 400
Altron™ PC, Sultron® PPSU, Duratron® U1000 PEI, Sultron® PSU	10 - 15	0 - 15	8 - 25	1,000- 3,000	25 - 40	0 - 8	4 - 6	50 - 400
Ertalon® 66 GF30 PA6, Duratron® T4301 / T4501 / T5530 PAI, Ketron® HPV / GF30 / CA30 / VMX PEEK, Techtron® HPV PPS, Semitron® ESd410C / 520 HR	10 - 15	0 - 15	8 - 25	1,000- 3,000	25 - 40	0 - 8	4 - 6	50 - 200
Duratron® CU60 PBI, Duratron® PI, Fluorosint® MT-01 PTFE	10 - 15	0 - 15	8 - 25	1,000- 3,000	25 - 40	0 - 8	2 - 3	25 - 100
Fluorosint® 135 / 207 / 500 PTFE, Semitron® ESd 500HR	10 - 15	0 - 15	8 - 25	1,000- 3,000	25 - 40	0 - 8	4 - 6	50 - 200

## Troubleshooting sawing

DIFFICULTY	MELTED SURFACE	ROUGH FINISH	BURRS AT EDGE OF CUT	CRACKING OF CHIPPING OF CORNERS	CHATTER
<b>Common cause</b>	<ul style="list-style-type: none"> <li>• Tool dull or heel rubbing</li> <li>• Insufficient side clearance</li> <li>• Feed rate too slow</li> <li>• Spindle speed too fast</li> </ul>	<ul style="list-style-type: none"> <li>• Feed too heavy</li> <li>• Incorrect clearance angles</li> <li>• Sharp point on tool (slight nose radius required)</li> <li>• Tool not mounted on center</li> </ul>	<ul style="list-style-type: none"> <li>• No chamfer provided at sharp corners</li> <li>• Dull tool</li> <li>• Insufficient side clearance</li> <li>• Lead angle not provided on tool (tool should ease out of cut gradually, not suddenly)</li> </ul>	<ul style="list-style-type: none"> <li>• Too much positive rake on tool</li> <li>• Tool not eased into cut (tool suddenly hits work)</li> <li>• Dull tool</li> <li>• Tool mounted below center</li> </ul>	<ul style="list-style-type: none"> <li>• Too much nose radius on tool</li> <li>• Tool not mounted solidly</li> <li>• Material not supported properly</li> <li>• Depth of cut too heavy (use 2 cuts)</li> </ul>

# Drilling

Plastics can build up heat very easily during drilling operations, especially when hole depths are greater than twice the diameter. Therefore a cooling liquid is generally recommended.


## Small diameter holes (0.5 – 25 mm diameter)

High speed steel twist drills generally work well. In order to improve heat and swarf removal, frequent pull-outs (peck-drilling) are necessary. A slow spiral (low helix) drill will allow for better swarf removal.


## Large diameter holes (25 mm diameter and larger)

It is advised to use drills with a thinned web (dubbed drill) in order to reduce friction and hence heat generation. Drill large holes stepwise: a bore diameter of 50 mm e.g. should be made by drilling successively with  $\varnothing$  12 mm and  $\varnothing$  25 mm, then expanding the hole further with larger diameter drills with a single boring tool.

For pilot holes for internal threads always check actual cutting size of drill. Most plastics close up after drilling. This can make taps tight.



Thinning of web is recommended on larger drills




Insert drill on solid pieces with right inserts



Spade drills can be useful

# Data drilling



	$\alpha$	$\gamma$	$\phi$	$s$	$v$	MATERIAL TOOL
Ertalon® PA / Nylatron® PA, TIVAR® UHMW-PE	5 - 10	3 - 5	90 - 120	0.1 - 0.3	50 - 100	HSS steel or carbide
Acetron® / Ertacetal® POM Semitron® ESd 225	5 - 10	3 - 5	90 - 120	0.1 - 0.3	50 - 100	HSS steel or carbide
Ertalyte® PET, Duratron® T4203 / 4503 PAI, Ketron® 1000 PEEK, Ketron® TX PEEK	5 - 10	3 - 5	90 - 120	0.1 - 0.3	50 - 80	Carbide
Altron™ PC, Sultron® PPSU, Duratron® U1000 PEI, Sultron® PSU	5 - 10	3 - 5	90 - 120	0.1 - 0.3	50 - 100	Carbide
Ertalon®66 GF30 / Nylatron® GF30 PA66 Duratron® T4301 / T4501 / T5530 PAI, Ketron® HPV / GF30 / CA30 / VMX PEEK, Techtron® HPV PPS, Semitron® ESd 410C / 520 HR	5 - 10	3 - 5	90 - 120	0.1 - 0.3	50 - 80	Carbide or PCD/ CVD
Duratron® CU60 PBI, Duratron® PI, Fluorosint® MT-01 PTFE	5 - 10	3 - 5	90 - 120	0.1 - 0.3	25 - 50	Carbide or PCD/ CVD
Fluorosint® 135 / 207 / 500 PTFE, Semitron® ESd 500HR	5 - 10	3 - 5	90 - 120	0.1 - 0.3	50 - 100	Carbide




# Troubleshooting drilling

DIFFICULTY	TAPERED HOLE	BURNED OF MELTED SURFACE	CHIPPING OF SURFACES	CHATTER	FEED MARKS OR SPIRAL LINES ON INSIDE DIAMETER
Common cause	<ul style="list-style-type: none"> <li>• Incorrectly sharpened oil</li> <li>• Insufficient clearance</li> <li>• Feed too heavy</li> </ul>	<ul style="list-style-type: none"> <li>• Wrong type drill</li> <li>• Incorrectly sharpened oil</li> <li>• Feed too light</li> <li>• Web too thick</li> </ul>	<ul style="list-style-type: none"> <li>• Feed too heavy</li> <li>• Clearance too great</li> <li>• Too much rake (thin web as described)</li> </ul>	<ul style="list-style-type: none"> <li>• Too much clearance</li> <li>• Feed too light</li> <li>• Drill overhang too great</li> <li>• Too much rake (thin web as described)</li> </ul>	<ul style="list-style-type: none"> <li>• Feed too heavy</li> <li>• Drill not centered</li> <li>• Drill ground off-center</li> </ul>
	OVERSIZE HOLES	UNDERSIZE HOLES	HOLES NOT CONCENTRIC	BURR AT CUT-OFF	RAPID DULLING OF DRILL
	<ul style="list-style-type: none"> <li>• Drill ground off-center</li> <li>• Web too thick</li> <li>• Insufficient clearance</li> <li>• Feed rate too heavy</li> <li>• Point angle too great</li> </ul>	<ul style="list-style-type: none"> <li>• Dull drill</li> <li>• Too much clearance</li> <li>• Point angle too small</li> </ul>	<ul style="list-style-type: none"> <li>• Feed too heavy</li> <li>• Spindle speed too slow</li> <li>• Drill-off too leaves nib which deflects drill</li> <li>• Web too thick</li> <li>• Drill speed too heavy at start</li> <li>• Drill not mounted on center</li> <li>• Drill not sharpened correctly</li> </ul>	<ul style="list-style-type: none"> <li>• Dull cut-off tool</li> <li>• 2. Drill does not pass</li> <li>• completely through piece</li> </ul>	<ul style="list-style-type: none"> <li>• Feed too light</li> <li>• Spindle speed too fast</li> <li>• Insufficient lubrication from coolant</li> </ul>

# Tapping/ Turning threads

- Use of spiral taps is recommended (not straight)
- Where possible use Rigid tap CNC Cycles
- Check pilot drill size
- Go for high quality taps where possible
- Turning threads should be straight forward
- Tools do not have to be as rigid as metal cutting tools



## Grades for grooving inserts

Stellram grades SP4030 and SP0436 for grooving inserts are PVD-coated grades with a micrograin substrate. They are designed for machining at higher speeds and lower feeds. These grades are ideal for use on stainless steels and ductile materials. See **inch** and **metric** grade descriptions.

## Ultra-Mini internal grooving tools


Our Ultra-Mini grooving inserts and tool holder's portfolio features replaceable carbide inserts with minimum bores down to 0.157" and groove widths from 0.039" to 0.078". The inserts are designed for internal machining of small diameters and are available in a range of reaches and groove width-to-length ratios. See the full inch and metric Ultra-Mini tool offering. Also see inch and metric Mini-Cut for internal grooving.



# Turning

## Tip Geometry

The continuous chip stream produced when turning and boring many thermoplastics can be handled well using a compressed air powered suction system (directly disposing the swarf into a container), in this way avoiding the chip wrapping around the chunk, the tool or the workpiece.



## Turning tips

- Machines should have cavernous area for swarf
- Avoid conveyor belts
- For Tubes you can bore one end and put a blank in to support clamp force of jaws
- Consider fixed pressure jaws on new machines
- Crawford Collets very good for plastic
- Use tip designed for non-ferrous metals such as Aluminum or Brass
- Best finish is achieved with 0.8 rad on tips
- Use hand diamond tools to polish grind marks
- Sometimes it is worth grinding insert tips on top face to sharpen front edge
- For improved tolerances, rough out large sections and leave for 24 hours
- Most diameters will grow so aim for lowest dimension when setting
- Consider doing capability studies on your machines
- Use sliding head for small long sections

## Troubleshooting turning



### Turning & Boring


DIFFICULTY	MELTED SURFACE	ROUGH FINISH	BURRS AT EDGE OF CUT	CRACKING OF CHIPPING OF CORNERS	CHATTER
Common cause	<ul style="list-style-type: none"> <li>• Tool dull or heel rubbing</li> <li>• Insufficient side clearance</li> <li>• Feed rate too slow</li> <li>• Spindle speed too fast</li> </ul>	<ul style="list-style-type: none"> <li>• Feed too heavy</li> <li>• Incorrect clearance angles</li> <li>• Sharp point on tool (slight nose radius required)</li> <li>• Tool not mounted on center</li> </ul>	<ul style="list-style-type: none"> <li>• No chamfer provided at sharp corners</li> <li>• Dull tool</li> <li>• Insufficient side clearance</li> <li>• Lead angle not provided on tool (tool should ease out of cut gradually, not suddenly)</li> </ul>	<ul style="list-style-type: none"> <li>• Too much positive rake on tool</li> <li>• Tool not eased into cut (tool suddenly hits work)</li> <li>• Dull tool</li> <li>• Tool mounted below center</li> </ul>	<ul style="list-style-type: none"> <li>• Too much nose radius on tool</li> <li>• Tool not mounted solidly</li> <li>• Material not supported properly</li> <li>• Depth of cut too heavy (use 2 cuts)</li> </ul>



### Parting (Cutting-off)

DIFFICULTY	MELTED SURFACE	ROUGH FINISH	SPIRAL MARKS	CONCAVE OR CONVEX SURFACES	NIBS OR BURRS AT CUT-OFF POINT	BURNS ON OUTSIDE DIAMETER
Common cause	<ul style="list-style-type: none"> <li>• Dull tool</li> <li>• Insufficient side clearance</li> <li>• Insufficient coolant supply</li> </ul>	<ul style="list-style-type: none"> <li>• Feed too heavy</li> <li>• Tool improperly sharpened</li> </ul>	<ul style="list-style-type: none"> <li>• Tool rubs during its retreat</li> <li>• Burr on point of tool</li> </ul>	<ul style="list-style-type: none"> <li>• Point angle not great enough</li> <li>• Tool not perpendicular to spindle</li> <li>• Tool deflecting</li> <li>• Feed tool heavy</li> <li>• Tool mounted above or below center</li> </ul>	<ul style="list-style-type: none"> <li>• Point angle not great enough</li> <li>• Dull tool</li> <li>• Feed too heavy</li> </ul>	<ul style="list-style-type: none"> <li>• No chamfer applied before cut-off</li> <li>• Dull tool</li> </ul>


# Data turning




	$\alpha$	$\gamma$	$\eta$	$s$	$v$	MATERIAL TOOL
Ertalon® PA / Nylatron® PA, TIVAR® UHMW-PE	5 - 15	0 - 10	0 - 45	0.05 - 0.5	200 - 500	HSS steel or carbide
Acetron® / Ertacetal® POM Semitron® ESd 225	5 - 15	0 - 10	0 - 45	0.05 - 0.5	200 - 500	HSS steel or carbide
Ertalyte® PET, Duratron® T4203 / 4503 PAI, Ketron® 1000 PEEK, Ketron® TX PEEK	5 - 15	0 - 10	0 - 45	0.05 - 0.5	200 - 400	Carbide
Altron™ PC, Sultron® PPSU, Duratron® U1000 PEI, Sultron® PSU	5 - 15	0 - 10	0 - 45	0.05 - 0.4	200 - 400	Carbide
Ertalon®66 GF30 / Nylatron® GF30 PA66 Duratron® T4301 / T4501 / T5530 PAI, Ketron® HPV / GF30 / CA30 / VMX PEEK, Techtron® HPV PPS, Semitron® ESd 410C / 520 HR	5 - 15	0 - 10	0 - 45	0.05 - 0.3	100 - 200	Carbide or PCD/CVD
Duratron® CU60 PBI, Duratron® PI, Fluorosint® MT-01 PTFE	5 - 15	3 - 5	0 - 45	0.05 - 0.2	25 - 100	Carbide or PCD/CVD
Fluorosint® 135 / 207 / 500 PTFE, Semitron® ESd 500HR	8 - 12	0 - 5	0 - 45	0.05 - 0.4	150 - 400	Carbide

# Milling

- Machines should have cavernous area for swarf.
- Use milling cutters with less teeth, higher helix and good clearances.
- Avoid conveyor belts.
- For milling machines consider vacuuming dry chips.
- Use of Vacuum plates recommended for plate parts.
- Parts can be further supported with surrounds on vacuum plate.
- Avoid machining too much on one side of flat plates.
- Even stress out where pockets are required on one side with opposing face grooves.
- Consider using round billets in some cases to overcome small volume restrictions.




## Climb milling (recommended)




Small break, less heat, better finish

## Conventional milling (not recommended)




Large break, more heat, worse finish

# Data milling



	$\alpha$	$\gamma$	$s$	$v$	MATERIAL TOOL
Ertalon® PA / Nylatron® PA, TIVAR® UHMW-PE	5 - 15	0 - 15	$\leq 0.5$	200 - 500	HSS steel or carbide
Ertacetal® POM, Semitron® ESd 225	5 - 15	0 - 15	$\leq 0.5$	200 - 400	HSS steel or carbide
Ertalyte® PET, Duratron® T4203 / 4503 PAI, Ketron® 1000 PEEK, Ketron® TX PEEK	5 - 15	0 - 15	$\leq 0.4$	150 - 300	Carbide
Altron™ PC, Sultron® PPSU, Duratron® U1000 PEI, Sultron® PSU	5 - 15	0 - 15	$\leq 0.4$	200 - 400	Carbide
Ertalon® 66 GF30 PA6, Duratron® T4301 / T4501 / T5530 PAI, Ketron® HPV / GF30 / CA30 / VMX PEEK, Techtron® HPV PPS, Semitron® ESd 410C / 520 HR	5 - 15	0 - 15	$\leq 0.3$	75 - 150	Carbide or PCD/CVD
Duratron® CU60 PBI, Duratron® PI, Fluorosint® MT-01 PTFE	5 - 15	0 - 15	$\leq 0.15$	25 - 100	Carbide or PCD/CVD
Fluorosint® 135 / 207 / 500 PTFE, Semitron® ESd 500HR	5 - 15	0 - 15	$\leq 0.3$	100 - 250	Carbide

# Best tolerances at MCG Engineered Solutions



These extra-precise tolerances can require special tooling and challenging machining steps which may lead to extra costs.

SIZE	HDPE	PET/ PC/ PEEK/ FL500/ PPS/ PEI / PPSU/ PSU/ PC	PA/ POM/ FL207	PEEK WITH FILLERS	PAI / PBI
1	0.05	0.02	0.02	0.02	0.02
5	0.05	0.02	0.02	0.02	0.02
10	0.05	0.02	0.03	0.02	0.02
15	0.05	0.03	0.03	0.02	0.02
20	0.05	0.03	0.03	0.03	0.02
25	0.05	0.03	0.04	0.03	0.03
30	0.06	0.03	0.04	0.03	0.03
35	0.06	0.03	0.04	0.03	0.03
40	0.07	0.04	0.05	0.03	0.03
45	0.08	0.04	0.05	0.03	0.03
50	0.08	0.04	0.05	0.03	0.03
60	0.10	0.04	0.06	0.04	0.03
70	0.11	0.05	0.07	0.04	0.04
80	0.12	0.05	0.07	0.04	0.04
90	0.13	0.06	0.08	0.05	0.04
100	0.15	0.06	0.09	0.05	0.04
110	0.16	0.07	0.09	0.05	0.05
120	0.17	0.07	0.10	0.05	0.05
130	0.18	0.07	0.10	0.06	0.05
140	0.20	0.08	0.11	0.06	0.05
150	0.21	0.08	0.12	0.06	0.05
160	0.22	0.09	0.12	0.07	0.06
170	0.23	0.09	0.13	0.07	0.06
180	0.25	0.09	0.14	0.07	0.06
190	0.26	0.10	0.14	0.08	0.06
200	0.26	0.10	0.15	0.08	0.07

## Thread inserts

Most of our engineering do not need thread inserts, but where there are strong vibrations or repeated clamping and unclamping.

### Most popular is self tapping – Tappex although be cautious

- If using slotted inserts – pre tap some of thread
- Check that there is no closure after insertion
- Consider inserts with cross hole to cut

### Some can be heat inserted but this is slower and ok for GEP

- Use of spiral taps is recommended (Not Straight)
- Where possible use Rigid tap CNC Cycles
- Check pilot drill size
- Go for high quality Taps where possible
- Turning threads should be straight forward
- Tools do not have to be as rigid as metal cutting tools



## Deburring

- Most common is to use sharp knives or rotary hook
- Important to have sharpness
- Counter sink tools like this are recommended as they do not cut too deep or chatter
- Hard plastics can be lightly abraded with Wet & Dry
- Rotary stones can be effective on some plastics
- Hot air good for complex GEP profiles






# General rules

---

- Consider rod as well as plate
- Machine equal to nit line
- If you have to machine pockets perform intermediate steps




## Example

---

### Solutions


1. Use Cast Nylon Plate
2. Cut section from so that center of extrusion is through symmetrical section. (90° to cut out)
3. Start with thickest plate and move extrusion line away from machined features.
4. Machine slots/ grooves in opposite face.
5. Balanced machining on both sides of the shape's centerline can also help prevent warpage.



# Annealing

## Better flatness and tighter tolerances

Extremely close-tolerance parts requiring precision flatness and non-symmetrical contour sometimes require intermediate annealing between machining steps. Improved flatness can be attained by rough machining, annealing and finish machining with a very light cut.



## Recommended annealing procedure

- T1:** Heat-up time (heating rate: 10-20 °C/h)
- T2:** Hold-time  
depends on the wall thickness: 10 min/mm
- T3:** Cool-down time (cooling rate: 5-10 °C/h)
- T4:** Additional time required to establish room temperature  
depends on the wall thickness: 3 min/mm


## Annealing tips

When pre-machining, leave enough oversize to allow machining to final sizes after annealing.

Fixturing parts to desired shape or flatness during the entire annealing cycle often proves advantageous.

Do not unfix until parts have completed entire annealing cycle and cooled down slowly to the touch.

Make sure that temperatures are uniform and within  $\pm 3^\circ\text{C}$  all over the oven or the oil bath at all times during annealing process.



MATERIALS	HEAT-UP	HOLD TEMPERATURE	HOLD-TIME (T2)	COOL DOWN	ENVIRONMENT*
PA	10 – 20°C / h	150°C	10 min / mm	5 – 10°C / h	air, nitrogen or oil
POM	10 – 20°C / h	150°C	10 min / mm	5 – 10°C / h	air, nitrogen or oil
PET	10 – 20°C / h	150°C	10 min / mm	5 – 10°C / h	air, nitrogen or oil
PE- (U)HMW	10 – 20°C / h	120°C	10 min / mm	5 – 10°C / h	air, nitrogen or oil
PC	10 – 20°C / h	130°C	10 min / mm	5 – 10°C / h	air or nitrogen
PEEK	10 – 20°C / h	250°C	10 min / mm	5 – 10°C / h	air or nitrogen
PPS	10 – 20°C / h	200°C	10 min / mm	5 – 10°C / h	air or nitrogen
PPSU	10 – 20°C / h	200°C	10 min / mm	5 – 10°C / h	air or nitrogen
PEI	10 – 20°C / h	200°C	10 min / mm	5 – 10°C / h	air or nitrogen
PSU	10 – 20°C / h	170°C	10 min / mm	5 – 10°C / h	air or nitrogen

# Summary

---

## **When machining MCG stock shapes remember...**

- Thermal expansion rate is up to 10x higher with plastics than metals
- Plastics lose heat more slowly than metals, so avoid localized overheating
- Softening (and melting) temperatures of plastics are much lower than metals
- Plastics are much more elastic than metals

Because of these significant differences you may wish to experiment with fixtures, tool materials, angles, speeds and feed rates to obtain optimal results.

# Get in touch

## North America

Mitsubishi Chemical  
Advanced Materials Inc.

2120 Fairmont Avenue  
PO Box 14235 — Reading,  
PA 19612-4235  
Tel: 800 366 0300  
+1 610 320 6600

## Europe

Mitsubishi Chemical  
Advanced Materials NV

Galgenveldstraat 12  
8700 Tielt, Belgium  
Tel: +32 051 42 35 11

## Asia-Pacific

Mitsubishi Chemical  
Advanced Materials Asia Pacific Ltd.

Unit 7B, 35/F, Cable TV Tower,  
9 Hoi Shing Road,  
Tsuen Wan, Hong Kong  
Tel: +852 2470 26 83



Belgium | Brazil | China | France | Germany | Hong Kong | Hungary | India | Italy | Japan | Korea | Mexico  
South Africa | Switzerland | The Netherlands | United Kingdom | United States Of America

All statements, technical information and recommendations contained in this publication are presented in good faith and are, as a rule, based upon tests and such tests are believed to be reliable and practical field experience. The reader, however, is cautioned, that Mitsubishi Chemical Advanced Materials does not guarantee the accuracy or completeness of this information.

It is the customer's responsibility to determine the suitability of Mitsubishi Chemical Advanced Materials' products in any given application. Acetron®, Altron™, Duratron®, Ertacetal®, Ertalon®, Ertalyte®, Flextron™, Fluorosint®, Ketron®, Nylatron®, Sultron®, QuickSilver®, Semitron®, Techtron® and TIVAR® are registered trademarks of the Mitsubishi Chemical Advanced Materials group.

Design and content created by Mitsubishi Chemical Advanced Materials and protected by copyright law. Copyright © 2022 Mitsubishi Chemical Advanced Materials. All rights reserved.